

## 6833/,(5¶6 1'( \$33529\$/ 67\$7(0(17

## Supplier: Element Rancho Dominguez

The following company has been audited and approved:

Element Rancho Dominguez Rancho Dominguez, CA

Julie Nguyen - Quality Representative. Bob Olevson ±Quality Manager Juan Gonzalez ±NDT Level III ASNT # 180022

TCI 2.0 Rev E ±Certification Procedure of NDT Personnel

Inspection Methods Approved:

Magnetic Particle Inspection

Ultrasonic Inspection

Liquid Penetrant Inspection

**Visual Inspection** 

I find the above in compliance with the requirements of the special process procedure SOUWI-009Band approve this vendor to perform the N.D.E. method(s) noted above for GE O&G-VGS.

This vendor will perform NDE work to GE VGS specifications that are directly applicable to the contract or services as required. Were new NDE personnel or upgrades of NDE program occurs a copy of change shall be maintained by the supplier and immediately available for review.

La Cadille

& KULV ' '¶ \$ ASNH ODE Level III ASNT # 56875